





Fepic®



WASHING INSTRUCTIONS

DO NOT USE ANY TYPE OF BLEACH OR STAIN REMOVING CHEMICALS
BEFORE DYEING / SET DYEING FABRIC SHOULD BE DRYING IN SHADE
(ALL COMPONENTS SEPARATELY) FOR 14 HOURS
DO NOT TIE HOT CABLES IN TOWELS THEM IN DRYER TO AVOID COPY MARKS
WASH COLOURED AND WHITE FABRICS SEPARATELY
IRON CLOTHES AT MEDIUM TEMPERATURE (DO NOT USE FABRIC IRONER DRYER)
(EXTRA LABELS, WASHING AND ACCESSORIES ARE NOT INCLUDED)

D-5171 B