







DO NOT USE TYPE OF BLEACH OR STAIN REMOVING CHEMICALS
BEFORE CUTTING / STITHING, FABRIC SHOULD BE SMOKED BE SOAKED IN WATER
( ALL COMPONENTS SEPARATELY) FOR 15 MINUTES
DO BOT KEEP WET FABRIC IN TWISTED FROM IN ORDER TO AVOID COPY MARKS I
IRON CLOTHES AT MODRATE TEMPERATURE IO NOT DRY FABRIC IN DIRECT SUNLIGHT
( EXTRA LACES, HANGINGS AND ACCESSORIES ARE NOT INDUDED )

















ON OT USE TYPE OF BLEACH OR STAIN REMOVING CHEMICALS
BEFORE CUTTING / STITHING., FABRIC SHOULD BE SMOKED BE SOAKED IN WATER
( ALL COMPONENTS SEPARATELY) FOR 15 MINUTES
DO BOT KEEP WET FABRIC IN TWISTED FROM IN ORDER TO AVOID COPY MARKS I
IRON CLOTHES AT MODRATE TEMPERATURE IO NOT DRY FABRIC IN DIRECT SUNLIGHT
( EXTRA LACES, HANGINGS AND ACCESSORIES ARE NOT INDUDED )














DO NOTUSE TYPE OF BLEACH OR STAIN REMOVING CHEMICALS
BEFORE CUTTING / STITHING; FABRIC SHOULD BE SMOKED BE SOAKED IN WATER
( ALL COMPONENTS SEPARATELY ) FOR 15 MINUTES
DO BOT KEEP WET FABRIC IN THISTED FROM IN ORDER TO AVOID COPY MARKS I
IRON CLOTHES AT MODRATE TEMPERATURE I DO NOT DRY FABRIC IN DIRECT SUNLIGHT
( EXTRA LACES, HANGINGS AND ACCESSORIES ARE NOT INDUDED )



















DO NOT USE TYPE OF BLEACH OR STAIN REMOVING CHEMICALS
BEFORE CUTTING / STITHING, FABRIC SHOULD BE SMOKED BE SOAKED IN WATER
( ALL COMPONENTS SEPARATELY) FOR 15 MINUTES
DO BOT KEEP WET FABRIC IN TWISTED FROM IN ORDER TO AVOID COPY MARKS I
IRON CLOTHES AT MODRATE TEMPERATURE IO NOT DRY FABRIC IN DIRECT SUNLIGHT
( EXTRA LACES, HANGINGS AND ACCESSORIES ARE NOT INDUDED )





